




[illegible]

7. The shell sealing area needs to be cooling when welding refrigerant connectors.

[illegible]