



# Operation Manual of SH101 Farmer Thermometer and Hygrometer

## Outlook


- ① MAX/MIN : Short press the button to display the highest / lowest temperature & humidity records. Long press (press and hold for 2 seconds or longer) to clear the memory.
- ② ADJ : 12/24 hours switch  
Work as Adjust Key when in SET mode  
Work as alarm ON/OFF when in Clock Alarm mode.
- ③ MODE : Short Press: Select the display mode of clock or alarm clock.  
Long Press: Enter the setting display of the mode you choose.
- ④ Plug Socket: For outdoor temperature sensor plugged in
- ⑤ °C/°F: Switchover of Fahrenheit or Celsius display
- ⑥ Battery cover    ⑦ Wall mount holes    ⑧ Suppressible table stand
- ⑨ Temperature sensor probe with 3m long cable



## LCD Screen Display



## Sensor Assembling



Please assemble the temperature sensor cable before using the product.

## Time Setting

- ① Under clock mode, long press [MODE] to enter the time setting. Digits "00" blink, then short press [ADJ] to set minute value.
- ② Short press [MODE] to enter hour setting. Digits "12" blink, press [ADJ] to set hour value. Short press [MODE] to confirm.



## Alarm Clock Setting

- ① Under Alarm Clock mode, long press [MODE] to enter alarm clock setting. Digits "00" blink, then short press [ADJ] to set minute value.
- ② Short press [MODE] to enter hour setting. Digits "12" blink, then short press [ADJ] to set hour value. Short press [MODE] to confirm.



Alarm is on when the  appears on the LCD display.

## Mode of time and alarm clock

Short press the [MODE] to switch Clock Mode or Alarm Clock mode. If choose the Clock Mode, the symbol "⌚" blinks. If choose the Alarm Clock mode, "AL" appears, the symbol "⌚" doesn't blink.

**Notice:** Under the Alarm Clock mode, if there is no operation for 2 minutes, it will back to Clock mode automatically.

## ON/OFF Alarm Clock

When Alarm Clock setting is finished, short press [ADJ] to turn on or turn off the clock alarm.

**Notice:** If there is no operation for 2 minutes, it will back to Clock mode automatically.

## Review / Delete

Press [MAX/MIN] button, you can check the max/min temperature and humidity, long press [MAX/MIN] for 2 seconds to delete the records.

## Convert °C/°F

Press [°C/°F] to switch Fahrenheit or Celsius display