



Statement Of Compliance

No.: 4790783741.1-S

Issue Date: April 21, 2025

Product Name : Safety light curtain

Model No. : EQC 06/40-200BB-R, EQC 06/40-200BB-E,
EQA TT/UU-VVVVWXY-Z, EQRF TT/UU-VVVVWXY-Z,
EQRF TT/UU-VVVVWXY-Z, EQC TT/UU-VVVVWXY-Z, EQZ
TT/UU-VVVVWXY-Z, EQCE TT/UU-VVVVWXY-Z, EQT TT/
UU-VVVVWXY-Z, EQL TT/UU-VVVVWXY-Z, EQM TT/UU-
VVVVWXY-Z, EQBT TT/UU-VVVVWXY-Z, EQS TT/UU-
VVVVWXY-Z, EKT UU/TT-VVVVWXY-Z, EFT UU/TT-
VVVVWXY-Z, EQSA TT/UU-VVVVWXY-Z, EQT4 TT/UU-
VVVVWXY-Z, EQO TT/UU-VVVVWXY-Z (Refer to report for
details)

Applicant : Dongguan Dadi Electronic Technology Co.,Ltd.

Manufacturer : Dongguan Dadi Electronic Technology Co.,Ltd.

Standards : FCC Part 15, Subpart B; ANSI C63.4-2014

We here certify that the above product complied with FCC official limits.
These products might be marketed in the US accordance to FCC rule
based on the standard FCC PART 15 Subpart B and ANSI C63.4-2014.

The test data & results are issued on the test report No.: 4790783741.1

UL Verification Services (Guangzhou)
Co., Ltd.Song Shan Lake Branch

Building 10, Innovation Technology Park,
No. 1, Li Bin Road, Song Shan Lake Hi-
Tech Development Zone Dongguan,
523808, People's Republic of China

Tel: +86 769 22038881

Fax: +86 769 33244054

UL Verification Services (Guangzhou)
Co., Ltd.Song Shan Lake Branch

Stephen Guo

Laboratory Manager

The Statement is based on a single evaluation of one sample of the above-mentioned
products. It does not imply an assessment of the whole production and does not
permit the use of the test lab logo.