



国际汽车配件（中国）有限公司

INTERNATIONAL AUTO PARTS (CHINA) LIMITED

Add: #37 Hongyun auto parts Square,Guangyuan Mid
Road ,baiyun,Guangzhou,Guangdong,China

Tel: 0086-20-86359046 **Fax:**0086-20- 26296679

10PA15C for Toyota Landcruiser Hilux Dyna Mitsubishi Pajero

Kia compressor

Specification:

Model number: INTL-XZC351M

Type: 10PA15C

Grooves: 1PK

clutch DIA: 125mm

Voltage: 12V

Oem:

447300-1170

4473001170

920423

92-0423

550049

920423

550049

447200944

4472000996



Can be used for:

1985-1997 Toyota Townace YR39

1990-1992 Toyota Landcruiser FJ70 73 75

1993-1997 Toyota Hilux LN105 106 111

1993-1995 Dyna LY 61

1997- Toyota Hilux LN147 152 167 172

1993-1997 Mitsubishi NJ-NK 3lt, 3.5lt V6

2001-2010 Kia Magentis L4 2.4L



MS Doreen

International Auto part(China) Limited

Tel: 0086 20 36681376 /+86-15920387684

Whatsapp: +86-15920387684

Skype: intl.doreen

Web : www.intl2008.com

